

Firmware Revision Info:

DMC-14x5 Controller

New feature Dec 22, 2006 - Rev 1.0i:

- No new features added

New feature Jan 5, 2005 - Rev 1.0h:

- Optimized cornering motion profile

New feature July 17, 2003 - Rev 1.0g:

- Added SA command
- Added serial port handshake timeout
- Added BK and SL commands to debug user application programs
- Added GA interrogation
- Added #AUTOERR special label
- Added _RS operand
- Added RS-1 function

New feature July 17, 2002 - Rev 1.0f:

- Double read of abort, limit and II inputs
- Allow product to designate a broadcast handle

New feature for Rev 1.0e Septemer 4, 2001:

- Added TH and WH commands
- Added IHh=>-3 to reset connection
- Added IHh= to reuse handle
- Added -5 and -6 to _IHh2 to indicate connection in progress
- Initialize tcperrhandle (_IA4) to -1

New feature for Rev 1.0d November 2, 2000:

- Operand `_EO` returns the state of echo-on
- Operand `_BV` returns the number of axes

New feature for Rev 1.0c September 5, 2000:

- ‘

New feature for Rev 1.0b July 12, 2000:

- ‘

New feature for Rev 1.0a May 13, 2000:

- Support of DB-14064 extended I/O daughter board