

Firmware Revision Info:

DMC-18x6 Controller

New feature for Rev 1.0c February 18, 2009:

- Added subroutine parameter passing

New features for Rev 1.0b February 6, 2008:

- Added DT-1 to pause contour buffer execution
- Added stop code 16 for stepper position error
- Added AF-1 for analog input sampling

New features for Rev 1.0a January 3, 2007:

- VV (Vector Velocity) command added for vector speed selection
- NB, NF and NZ maximum based on TM value

New feature for Rev 1.0 October 5, 2005:

- Firmware Released