

## **Firmware Revision Info:**

---

### **DMC-31x2/DMC-31x3 Controller**

#### ***New feature for Rev 1.0f December 22, 2006 :***

- No new features added

#### ***New feature for Rev 1.0e October 3, 2005 :***

- Added Stepper Motor Position Maintenance Mode (<http://www.galilmc.com/support/appnotes/optima/note2445.pdf>)
- Added ECAM with two linear segments (<http://www.galilmc.com/support/appnotes/optima/note2444.pdf>)
- Modified AU command for AMP-20542

#### ***January 5, 2005 - Rev 1.0d:***

- No new features added

#### ***March 15, 2004 - Rev 1.0c:***

- Improved BS command for AMP-20540
- Added support for AMP-20640 (AG and LC)
- Added ELO support: Added TA3 and CN operand for abort input application program disable

#### ***March 15, 2004 - Rev 1.0a:***

- No new features added.

#### ***December 18, 2003 - Rev 1.0:***

- DMC-31x2/31x3 Controller Introduced