

**Firmware Revision Info:**

---

**DMC-41x3 Motion Controller**

***New features for Rev 1.1a1 May 4, 2011:***

- Modified BX Command Algorithm
- Added BX<n for BX pulse duration
- Added BI-1 for Galil Sine Amplifier Hall Commutation
- Added support for BC and BI with internal Sine Amplifiers

***New features for Rev 1.1a April 8, 2011:***

- Frequency Analysis Software support added
- AMP-43240, AMP-43540 and AMP-43640 support added

***New feature for Rev 1.0 September 28, 2010 :***

- Rev 1.0 firmware released